



Dredge Status:

RM 413.6, Furnal Island - Gov Mechanical

Channel Marker Status:

Be aware that buoys may be unreliable due to high flows and debris. Mariners should use caution.

Additional Risks / Concerns:

Web Information

For additional resources including **Navigation Notices**, see the link below:
<http://www2.mvr.usace.army.mil/NIC2/default.cfm>

For **Hydrographic Surveys** and **Dredging Schedule**, see the link below:
<http://www2.mvr.usace.army.mil/odrsurvey/default.cfm>

KEY

- ◇ Anticipated Dredging
- ★ Groundings
- △ Dredge
- Very Likely to be Problematic at Low Water
- Could be Problematic at Low Water
- Problem Resolved

Probable "Hot" Spots	R. Mile	Min dep @ low water	Problem On:	Dredge ETA	Dredge Complete	Dredge
	413.6		RDB	10-May	7-Jul	Gov Mech